0004

Page 1 of 1 Outgons C0150025

# **Suzanne Steab - January 2010 Inspection Report**

From:

Karl Houskeeper

To:

krus8416@aol.com; mark.reynolds@hiawathacoal.com; mnz@princeyeates.com

Date:

2/1/2010 11:29 AM

Subject:

January 2010 Inspection Report

CC:

 $ANGELANANCE@utah.gov; \ DARONHADDOCK@utah.gov; \ SUZANNESTEAB@utah.gov$ 

Attachments: Bear Canyon January 2010.pdf

Attached is the January 2010 inspection report for Bear Canyon.

Thanks, Karl



## State of Utah

## Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

## Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Permitee: HIAWATHA COAL CO INC

JON M. HUNTSMAN, JR. Governor GARY R. HERBERT Lieutenant Governor

Operator: HIAWATHA COAL CO INC

Site: BEAR CANYON MINE

Representatives Present During the Inspection: Company Mark Reynolds Resident Agent

OGM Karl Houskeeper Environmental Scientist III

Address: PO BOX 1240, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

### **Current Acreages**

10,991.83	Total Permitted Total Disturbed		
40.46			
	Phase I		
	Phase II		
	Phase III		

# **Inspection Report**

Permit Number:	C0150025			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, January 13, 2010			
Start Date/Time:	1/13/2010 8:30:00 AM			
End Date/Time:	1/13/2010 1:30:00 PM			
Last Inspection:	Tuesday, December 29, 2009			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 19 Deg. F. InspectionID Report Number: 2243

Accepted by: jhelfric

1/25/2010

Mineral Ownership	Types of Operation		
☑ Federal	✓ Underground		

✓ Underground ☐ Surface ☐ State County ☐ Loadout

☐ Processing □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

☐ Other

Karl Houskeeper, Environmental Scientist III

Wednesday, January 13, 2010 Date

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 13, 2010

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>✓</b>		<b>V</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing	<b>V</b>		<b>V</b>	
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 13, 2010

Page 3 of 3

## 2. Signs and Markers

The mine ID sign is located at the point of public access. Parts of the sign are missing (ie, part of the phone number). The sign is legible,

## 4.a Hydrologic Balance: Diversions

Several diversions were identified that had snow pushed into their reaches. The snow needs top be removed to prevent any blockages when it begins to thaw out.

# 16.a Roads: Construction, Maintenance, Surfacing

Snow has been pushed on the main access roads and portal road.